

## BUILDING SAFETY CERTIFICATE

No.

Dated: .....

It is certified that the existing building St. Mary's Higher Secondary School  
 (name of the building or premises) at Latika Complex, Nyamo Lolka Road  
Dimapur, Nagaland (address) is having block(s)/Floor(s) as per  
 details below:

| Detail of Block(s) in school | Block (1) | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|------------------------------|-----------|-----------|-----------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | 5         | 3         | 3         |           |           |           |

The building is owned/occupied by St. Mary's Higher Secondary School (name of the Institution)  
 have complied with the Building safety requirements in accordance with National Building  
 code Rules, and verified by the officers concerned of ..... (Name of  
 Department/ Govt.) on 1st May 2026 (date of inspection) in the presence of  
Mr. Kundan Gupta, Dimapur, Nagaland (name and addresses  
 of the Manager/Secretary or his representative) and that the building/premises is fit for  
 occupancy for running school with effect from 14th May 2026 for a period of  
50 years in accordance with rule and subject to compliance of the specific  
 conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on ..... at ..... by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet  
 for detail.

Signature with Seal :

Name :

Designation :

Name &amp; Address of Department/ Office:

Er. Chandan Gupta  
 B.TECH (CIVIL) ; A.M.I.E. (I) ; M.B.A. (Projects Mgt.)  
 Regd.No. AM-1374527  
 Structural Consultant Engineer  
 STAAD. Pro Analyst.  
 TECH'S VISION CONSULTANTS  
 Dimapur : Nagaland